

Condition	Radiant Flux (Watts)	Luminous Flux (lumens)	% Loss (overall)
With Optics	2.16	750	16.0%
Without Optics	2.76	894	--

Table 9: Measured Optical Efficiency

Optical Efficiency = lumens with optic / lumens without  
 = 750/894  
 = **84.0%**